

<b>PCN Number:</b>	20140930002	<b>PCN Date:</b>	10/06/2014
<b>Title:</b>	CC3000MOD Production Firmware update		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Phone:</b>	+1(214) 480-6037
<b>Dept:</b>	Quality Services		
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input checked="" type="checkbox"/>	Software	<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process
<b>PCN Details</b>			
<b>Description of Change:</b>			
Texas Instruments Incorporated is announcing an information only notification concerning CC3000 module Firmware update from Version 1.10.1 to Version 1.12.			
<b>Reason for Change:</b>			
<p>The CC3000 module Firmware update addresses several known issues, also includes stability improvements and changes required for ETSI 1.8.1 certification. Currently compliant to ETSI 1.7.1 with an ETSI mandate for all products shipping to Europe on or after Jan 1, 2015 requiring compliance to ETSI 1.8.1, this Firmware update satisfies that requirement.</p> <p>A complete list of all changes can be found in the Wiki based Release Notes here:  <a href="http://processors.wiki.ti.com/index.php/CC3000_Release_Notes#Version_1.12">http://processors.wiki.ti.com/index.php/CC3000_Release_Notes#Version_1.12</a>:</p>			
<b>Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):</b>			
ETSI 1.8.1 compliance.			
<b>Changes to product identification resulting from this PCN:</b>			
None.			
<b>Product Affected:</b>			
CC3000MODR CC3000MODT CC3000MOD			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>