



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000878

DATE: 27-Nov-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX3204EEWT+	N/A			Part reactivated from prior notice: M000815
Reactivation	MAX3204EEWT+T	N/A			Part reactivated from prior notice: M000815
Reactivation	MAX4090EUT+	N/A			Part reactivated from prior notice: M000854
Reactivation	MAX4090EUT+T	N/A			Part reactivated from prior notice: M000857
Reactivation	MAX98400BETG+	N/A			Part reactivated from prior notice: M000874
Discontinuance	806-0624-01	N/A	27-Nov-2019	28-May-2020	Part can no longer be manufactured
Discontinuance	DS5240F-125+	N/A	27-Nov-2019	28-May-2020	Part can no longer be manufactured
Discontinuance	DS5240F-1N5+	N/A	27-Nov-2019	28-May-2020	Part can no longer be manufactured
Discontinuance	MAX20030ATMB/V+	MAX20030BATMB/V+	27-Nov-2018	28-May-2020	The part was not released
Discontinuance	MAX20030ATMC/V+	MAX20030BATMC/V+	27-Nov-2018	27-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX20030ATMC/V+T	MAX20030BATMC/V+T	27-Nov-2018	27-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX20031ATMB/V+	MAX20031BATMB/V+	27-Nov-2018	28-May-2020	Part can no longer be manufactured
Discontinuance	MAX20031ATMB/V+T	MAX20031BATMB/V+T	27-Nov-2018	27-Nov-2018	Part can no longer be manufactured
Discontinuance	VSC452XHW-05	N/A	01-May-2019	28-May-2020	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 28-Dec-2018