


PCN Number:	20180820001	PCN Date:	August 23, 2018
Title:	Datasheet for TCA4311A		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
		<input type="checkbox"/>	Wafer Bump Site
		<input type="checkbox"/>	Wafer Bump Material
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Site
		<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Fab Process
Notification Details			
Description of Change:			
<p>Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.</p> <p style="text-align: center;">Reissue Original PCN; possible system error</p>			
 <div style="float: right;"> TCA4311A <small>SCPS226C – JANUARY 2011 – REVISED AUGUST 2018</small> </div>			
Changes from Revision B (October 2014) to Revision C			
			Page
•	Moved T_{stg} to the <i>Absolute Maximum Rating</i> table		4
•	Changed the <i>Handling Rating</i> table To: <i>ESD Ratings</i>		4
•	Added <i>Missing ACK Event</i> section		10
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
TCA4311A	SCPS226B	SCPS226C	
These changes may be reviewed at the datasheet links provided.			
http://www.ti.com/product/TCA4311A			
Reason for Change:			
To accurately reflect device characteristics.			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
TCA4311ADGKR	TCA4311ADR		

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com