

To: Distribution

Please be informed Toshiba has announced discontinuation on the following product(s) due to assembly machine discontinuation.

### Products

Item No	Generic PN	Last Time Buy	Last Shipment	Replacement	* Substitution	** Reason
74HC139D(BJ)	74HC139D	12/31/2021	3/31/2022	-	0	4
74HC174D(BJ)	74HC174D	12/31/2021	3/31/2022	-	0	4
74HCT00D(BJ)	74HCT00D	12/31/2021	3/31/2022	-	0	4
74HCT02D(BJ)	74HCT02D	12/31/2021	3/31/2022	-	0	4
74HCT08D(BJ)	74HCT08D	12/31/2021	3/31/2022	-	0	4
74HCT32D(BJ)	74HCT32D	12/31/2021	3/31/2022	-	0	4
TC7WP3125FK(T5L,F)	TC7WP3125FK(T5L,F)	12/31/2021	3/31/2022	TC7WP3125FK,LF(CT)	1	4
TC7WPN3125FK(T5L,F)	TC7WPN3125FK(T5L,F)	12/31/2021	3/31/2022	TC7WPN3125FK,LF(CT)	1	4

### Last Time Buy (LTB) Option

Toshiba will support last time buy (LTB) orders received on or before the dates listed above (LTB Date). Last time buy orders for all affected products must be in place in total by LTB Date. Deliveries will be scheduled and advised accordingly after receipt of LTB orders. However, unforeseen circumstances might prevent Toshiba to support partially or fully on LTB orders. If such event occurs, we will notify you of our best support plan as soon as possible. Thank you for your understanding. Should you have any questions, please contact your sales representative.

Best Regards,

Logic Device, Discrete Business Unit

Toshiba America Electronic Components, Inc.

---

**\* Substitution Level**

0 = No Replacement P/N

1 = Package and characteristics are mostly same or better, not necessary to change other circuit to replace.

2 = Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.

3 = Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.

4 = Other reason.

**\*\* Reason**

1 Version Up

2 Chip Shrink

3 Integration of products

4 Discontinuation of Assembly Machine

5 No Order Forecast

6 Mask disposal rule applied

9 Others