

Product Obsolescence Notification

Issue Date: 29-July-2022

Dear Customer:

Broadcom regrets to announce the obsolescence of the following products:

Broadcom Part Numbers	Description	Suggested Replacement
ASMB-BTE1-ZB332	PLCC4,T/Mt,BB/WF Silicone RGB	ASMB-UTF0-0D20B
ASMB-TTBO-0A3A2	PLCC6,T/Mt,Tall RGB	ASMB-TTF2-0B20B
ASMT-AR00-ARS00	MS AV,1W Red	ASMT-AR00-AST00
ASMT-AR30-ARS00	MS AV,3W Red	ASMT-AR30-AST00
ASMT-JR10-ARS01	MS JD,1W Red	ASMT-JR10-AST01
ASMT-JR30-ARS01	MS JD,3W Red	ASMT-JR30-AST01
HDSP-5701-GH000	S4,0.56S,Yel,CA	HDSP-5701-HI000
HDSP-5703-GH000	S4,0.56S,Yel,CC	HDSP-5703-HI000
HDSP-5721-GH000	S4,0.56D,Yel,CA	HDSP-5721-HI000
HDSP-7401-EF000	S4,0.3M,Yel,CA	HDSP-7401-GH000
HDSP-7403-EF000	S4,0.3M,Yel,CC	HDSP-7403-GH000
HDSP-F301-EF000	S4,0.4S,Yel,CA	HDSP-F301-GH000
HDSP-F303-EF000	S4,0.4S,Yel,CC	HDSP-F303-GH000
HDSP-F303-EF016	S4,0.4S,Yel,CC	HDSP-F303-GH016
HLMF-K200#2UM	Lamp,3mm,Auto insert,GaP,HER	NA
HLMF-K200#2UP	Lamp,3mm,Auto insert,GaP,HER	NA
HLMF-K300#2UK	Lamp,3mm,Auto insert,GaP,Yel	NA
HLMF-K300#2UL	Lamp,3mm,Auto insert,GaP,Yel	NA
HLMF-K400#2UL	Lamp,3mm,Auto insert,GaP,Org	NA
HLMF-K500#2UL	Lamp,3mm,Auto insert,GaP,Grn	NA
HLMF-K500#2UP	Lamp,3mm,Auto insert,GaP,Grn	NA

Broadcom Part Numbers	Description	Suggested Replacement
HLMF-K505#2UK	Lamp,3mm,Auto insert,GaP,Grn	NA
HLMF-KG02	Lamp,3mm,45deg,AlInGaP,626nm Red	NA
HLMP-1301-HI000	Lamp,3mm,GaP,Red	HLMP-1301-HJ000
HLMP-1503-FH000	Lamp,3mm,GaP,Grn	HLMP-1503-EG000
HLMP-1503-FH0A2	Lamp,3mm,GaP,Grn	HLMP-1503-EG0A2
HLMP-1640-FH000	Lamp,3mm,5V RLED,GaP,Grn	HLMP-1640-EG000
HLMP-1700-EF0FH	Lamp,3mm,LC,GaP,Red	HLMP-1700-EG000
HLMP-3301-GI000	Lamp,5mm,GaP,Red	HLMP-3301-HJ000
HLMP-3301-GI0UK	Lamp,5mm,GaP,Red	HLMP-3301-HJ0UK
HLMP-3507-FG000	Lamp,5mm,GaP,Grn	HLMP-3507-EG000
HLMP-3950-MN000	Lamp,5mm,GaP,Grn,Standoffs	HLMP-3950-LN000
HLMP-4700-EG0FH	Lamp,5mm,LC,GaP,Red	HLMP-4700-EG000
HLMP-6400-JK000	Poly,Dome,GaP,Yel	NA
HLMP-D401-KM0FH	Lamp,5mm,GaP,Org	HLMP-D401-IJ0FH
HLMP-N305-G00DD	Lamp,3mm,GaP,Yel	NA
HLMP-N505-G00DD	Lamp,3mm,GaP,Grn	NA
HLMP-NG05	Lamp,3mm,45deg,AlInGaP,626nm Red	NA
HLMP-NG07-MQ000	Lamp,3mm,60deg,AlInGaP,626nm Red	NA
QDSM-591Z	IC Module,0.73in,10 Dgts,Multiclr,CC	NA
QDSP-U232	S4,0.3UM,HER,CC,T/S Black	NA
QLMP-4004	Lamp,5mm,HB,Biclr RedGrn	NA
QLMP-K506-FH0ED	Lamp,3mm,GaP,Grn	QLMP-K506-EG0ED
QLMP-NG98-L00TB	Lamp,3mm,45deg,AlInGaP,626nm Red	NA
QLMP-P395	Poly,Ftop,GaP,Yel	NA
QSMT-CB21	Chip,Top Mt,InGaN,Blue	HSMR-C020
QSMT-CB23	Chip,Top Mt,InGaN,Blue	HSMR-C020
QSMT-FG16-NIK00	Chip,AFA,Top Mt,InGaN,Grn	QSMT-FG16-NJM00
QSMT-FJ63-AFJ00	Chip,AFA,Top Mt,AlInGaP,Org	QSMT-FJ64-AGJ00

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Suggested Replacement
5082-7613	S4,0.3in,HER,CC,T/S Red	29 Jan 2023	29 Jul 2023	NA
5082-7623	S4,0.3in,Yel,CC,T/S Yel	29 Jan 2023	29 Jul 2023	NA
5082-7661	S4,0.43in,Yel,CA,T/S Yel	29 Jan 2023	29 Jul 2023	NA
5082-7663	S4,0.43in,Yel,CC,T/S Yel	29 Jan 2023	29 Jul 2023	NA
ASMT-CB20	Chip,Top Mt,InGaN,Blue	29 Jan 2023	29 Jul 2023	HSMR-C020
ASMT-SRB4-PW505	PLCC4 PN14,120VA,AllnGaP,Red	29 Jan 2023	29 Jul 2023	ASMT-SRB4-YW905
ASMT-URB4-PU802	PLCC2,T/Mt,Sil,120VA,AllnGaP,Red	29 Jan 2023	29 Jul 2023	ASMT-URB4-YU802
ASMW-LA00-AUW0E	2835 0.5W SMD-TLED	29 Jan 2023	29 Jul 2023	CSMW-LA00-AVX0E
ASMW-LH00-AUW0E	2835 0.5W SMD-TLED	29 Jan 2023	29 Jul 2023	CSMW-LH00-AUW0E
ASMW-LR00-ASU0E	2835 0.5W SMD-TLED	29 Jan 2023	29 Jul 2023	CSMW-LR00-ATV0E
ASMW-PWG4-NKNBE	2835 6V 1.0W White SMD-TLED	29 Jan 2023	29 Jul 2023	ASMW-PWG4-NKNBE
HDSP-3603	S4,0.3in,Grn,CC	29 Jan 2023	29 Jul 2023	NA
HDSP-3900	S4,0.8in,HER,CA,LDP	29 Jan 2023	29 Jul 2023	NA
HDSP-3905	S4,0.8in,HER,CC,LDP	29 Jan 2023	29 Jul 2023	NA
HDSP-F208	S4,0.4S,HER,Overflow,CC	29 Jan 2023	29 Jul 2023	NA
HDSP-N105	S4,0.8in,AlGaAs LC,CC,LDP	29 Jan 2023	29 Jul 2023	NA
HDSP-N150	S4,0.8in,AlGaAs,CA,LDP	29 Jan 2023	29 Jul 2023	NA
HLMP-EG2D-XY0DD	Lamp,5mm,AllnGaP,Red,23deg,tinted	29 Jan 2023	29 Jul 2023	HLMP-EG2B-XY0DD
HLMP-EG3H-WX0ZZ	Lamp,5mm,AllnGaP,Red,30deg	29 Jan 2023	29 Jul 2023	HLMP-EG3H-WX0DD
HLMP-EH1A-120DD	Lamp,5mm,AllnGaP,RedOrg,15deg	29 Jan 2023	29 Jul 2023	HLMP-EH1A-Z10DD
HLMP-EL2D-YZKDD	Lamp,5mm,AllnGaP,Amb,23deg,tinted	29 Jan 2023	29 Jul 2023	HLMP-EL2B-YZKDD
HLMP-EL3A-WXKZZ	Lamp,5mm,AllnGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3A-WXKDD
HLMP-EL3B-WXKZZ	Lamp,5mm,AllnGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3B-WXKDD
HLMP-EL3B-WXLDV	Lamp,5mm,AllnGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3B-WXLDLDD
HLMP-EL3Q-TV0DD	Lamp,5mm,AllnGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3G-VW0DD
HLMP-EL3Q-TVKDD	Lamp,5mm,AllnGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3G-VWKDD
HLMP-EL3Q-TVLDD	Lamp,5mm,AllnGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3G-VWLDD



Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Suggested Replacement
HLMP-EL3R-TV0DD	Lamp,5mm,AlInGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3H-VW0DD
HLMP-EL3R-TVKDD	Lamp,5mm,AlInGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3H-VWKDD
HLMP-EL3R-TVLDD	Lamp,5mm,AlInGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	HLMP-EL3H-VWLDD
HLMP-LM75-34BDD	Lamp,4mm,InGaN,Grn,40X100deg	29 Jan 2023	29 Jul 2023	HLMP-LM75-34CDD
HSMJ-A400-W00M1	PLCC4,PWR,T/Mt,120VA,AlInGaP2,Red Org	29 Jan 2023	29 Jul 2023	HSMJ-A412-YA0M1
HSMJ-A430-W50M1	PLCC4,PWR,T/Mt,30VA,AlInGaP,Rorg	29 Jan 2023	29 Jul 2023	HSMJ-A431-X90M1
HSMN-A430-V7YM2	PLCC4,PWR,T/Mt,30VA,InGaN,Blue	29 Jan 2023	29 Jul 2023	HSMN-A430-V50M2
QLMP-6437	Poly,Dome,GaP,Yel	29 Jan 2023	29 Jul 2023	NA
QLMP-CB2D-UVBDD	Lamp,5mm,InGaN,Blue,tnt,20deg	29 Jan 2023	29 Jul 2023	NA
QLMP-CB2D-UVCDD	Lamp,5mm,InGaN,Blue,tnt,20deg	29 Jan 2023	29 Jul 2023	NA
QLMP-CB8G-VWCDV	Lamp,5mm,InGaN,Blue,23deg	29 Jan 2023	29 Jul 2023	NA
QLMP-CM2D-Z1CDD	Lamp,5mm,InGaN,Grn,tnt,20deg	29 Jan 2023	29 Jul 2023	NA
QLMP-CM8D-Z1CDD	Lamp,5mm,tnt,InGaN,Grn,23deg	29 Jan 2023	29 Jul 2023	HLMP-CM3B-Z1CDD
QLMP-EL94-MNLDU	Lamp,5mm,AlInGaP,Amb,30deg	29 Jan 2023	29 Jul 2023	NA
QLMZ-EL2D-YZKDD	LampZ,5mm,AlInGaP,Amb,tnt,20deg	29 Jan 2023	29 Jul 2023	HLMP-EL2B-YZKDD
QLMZ-HG71-WZ0ZZ	LampZ,5mm,AlInGaP,Red,40X100deg	29 Jan 2023	29 Jul 2023	HLMP-HG71-WZ0ZZ
QLMZ-HL64-XYL00	LampZ,5mm,AlInGaP,Amb,40X100deg	29 Jan 2023	29 Jul 2023	HLMP-HL64-XYL00

Please provide your Broadcom Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy (LTB) order date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the Last Time Ship (LTS) date noted in the above table. Due to inherent variations in yields, Broadcom reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom's minimum order quantity (MOQ) requirements per the above table. All prior commitments regarding Broadcom's minimum order requirements do not apply to last time buy orders. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.