



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000852

DATE: 18-Apr-2017

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX16501V1EVKIT#	N/A			Part reactivated from prior notice: M000845
Reactivation	MAX16813TEVKIT#	N/A			Part reactivated from prior notice: M0008641
Reactivation	VSC452XHW-05	N/A			Part reactivated from prior notice: M000845
Discontinuance	MAX1448EVKIT	N/A	18-Apr-2017	18-Apr-2017	EVKIT is No Longer Supported
Discontinuance	MAX16833AUE/V+CFX	MAX16833AUE/V+TC1	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX16833AUE/V+TC0	MAX16833AUE/V+CLM	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX16833AUE/V+TCFX	MAX16833AUE/V+TC1	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX16833BAUE/V+CL	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX16833BAUE/V+TCL	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX194BMDE	N/A	18-Apr-2018	18-Oct-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX20053EVKIT#	MAX20050EVKIT#	18-Apr-2017	18-Apr-2017	EVKIT is No Longer Supported
Discontinuance	MAX2082EVKIT#	N/A	18-Apr-2017	18-Apr-2017	EVKIT is No Longer Supported
Discontinuance	MAX5679ETJ+	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX86110EFD+	MAX30101EFD+	18-Apr-2017	18-Apr-2017	The part was not released
Discontinuance	MAX9507ATE+	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX9507ATE+T	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX9516ALB+	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX9516ALB+T	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX9587AZT+	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX9587AZT+T	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX9633ATA+	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured
Discontinuance	MAX9633ATA+T	N/A	18-Apr-2018	18-Oct-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 19-May-2017