



Product Change Notice

PCN Number: 14-0414-02
Issue Date: 14-APRIL-2014

Exar Corporation

www.exar.com | Support: customersupport@exar.com

PRODUCTS AFFECTED:

SP34063AEN-L
SP34063AEN-L/TR

CHANGE CATEGORY:

- | | | |
|--|------------------------------------|---|
| <input checked="" type="checkbox"/> Material | <input type="checkbox"/> Process | <input type="checkbox"/> Package |
| <input checked="" type="checkbox"/> Design | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input type="checkbox"/> Other (specify) | | |

DESCRIPTION OF CHANGE:

- The SP34063A die has been revised to accommodate copper wire bonding assembly.

IMPACT OF CHANGE:

There will be no change to product form, fit or function.

TARGET IMPLEMENTATION DATE: 14-JULY-2014

Please contact customer support (customersupport@exar.com) for sample date availability or qualification data

PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.