

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN Number: #13-0028

Issue Date: **December 13, 2013**

Product(s) Affected: **See below**

Last Purchase Date: **June 13, 2014**

Last Shipment Date: **September 13, 2014**

Reason for Discontinuing Listed Products:

- Obsolete Design/Process Technology
- Obsolete Package/Assembly Technology
- No current or rapidly declining sales
- Other:

Pericom (PSC) Contact: Raul Aman

Title: Quality Assurance Director

Phone: 408 232-9100

Fax: 408-434-1040

eMail: PCN_PDN@pericom.com

*** Note:**

Pericom would like to notify all customers that products listed in the attached spreadsheet will be discontinued due to demand volume is not sufficient enough to justify the continuation of these products.

In some cases, availability may be limited, and the normal last time purchase and shipment methods may not be supported. Customers are encouraged to provide requirements as early as possible.

Pericom apologizes for any inconvenience this situation may cause.

Customer Acknowledgement:

Customer:

Name:

Title:

Date:

E-Mail:

Phone:

Fax:

Customers may use this form to acknowledge receipt of this notification, or can e-mail the Pericom contact noted above.

Customer Comments:

Pericom Internal Use Only:

Location: PSC PTI PSE-TW PSE-SD

PSETW PDN: N/A

PDN 13-0028, Affected Part Number

Product Line	Part Number	Product Family	Description	PkgLds	Comments for Customers
Clock	PI6C487016FBE	Clock Buffer	1to16 LVCMOS/LVTTL Clock Drive	FB48	No Replacement
Clock	PI6C487016FBEX	Clock Buffer	1to16 LVCMOS/LVTTL Clock Drive	FB48	No Replacement
Clock	PI6C557-06LE	Clock Buffer	2:1 MUX 1:4 PCI Express Gen 2 Zero Delay Buffer	L20	No Replacement
Clock	PI6C557-06LEX	Clock Buffer	2:1 MUX 1:4 PCI Express Gen 2 Zero Delay Buffer	L20	No Replacement
Clock	PI6C557-06LIE	Clock Buffer	2:1 MUX 1:4 PCI Express Gen 2 Zero Delay Buffer	L20	No Replacement
Clock	PI6C557-06LIEEX	Clock Buffer	2:1 MUX 1:4 PCI Express Gen 2 Zero Delay Buffer	L20	No Replacement
Clock	PI6CV847LE	Zero Delay Buffer	233 MHZ PLL CLock Driver	L24	No Replacement
Clock	PI6CV847LEX	Zero Delay Buffer	233 MHZ PLL CLock Driver	L24	No Replacement
Clock	PI6CV855LE	Zero Delay Buffer	170 MHZ 1:10 SSTV Clock Driver	L28	No Replacement
Clock	PI6CV855LEX	Zero Delay Buffer	170 MHZ 1:10 SSTV Clock Driver	L28	No Replacement
Clock	PI6CVF857AE	Zero Delay Buffer	DDR Clock Buffer SSTL2	A48	No Replacement
Clock	PI6CVF857AEX	Zero Delay Buffer	DDR Clock Buffer SSTL2	A48	No Replacement
Logic	PI74HSTL1212AE	ALVC	24-Bit BiDirectional Level	A64	No Replacement
Logic	PI74HSTL1212AEX	ALVC	24-Bit BiDirectional Level	A64	No Replacement
Switch	PI3A3159TEX	Analog Switch	3.3V SOTiny 0.4um, SPDT Analog	T06	No Replacement
Switch	PI3A3160ZEEX	Analog Switch	3.3V, 0.4-Ohm, Dual SPDT	ZE12	No Replacement
Switch	PI3B16226BE	Bus Switch	3.3v, Low Capacitance Bus Swit	B40	No Replacement
Switch	PI3B16226BEX	Bus Switch	3.3v, Low Capacitance Bus Swit	B40	No Replacement
Switch	PI3USB10LP-AZLEX	ASSP	Dual SPDT USB 2.0 Compliant Sw	ZL10	No Replacement
Switch	PI3USB2117ZLEX	ASSP	2L314-388-CBA/AA Dual SPST	ZL10	No Replacement