

Product / Process Change Notification



N° 2013-081-A

Dear Customer,

Please find attached our INFINEON Technologies PCN:

Design Change of Fluorescent Lamp Ballast Controller

Important information for your attention:

- Please respond to this PCN by indicating your decision on the approval form, sign it and return to your sales partner before **20. June 2014**.
- Infineon aligns with the widely-recognized JEDEC STANDARD "JESD46", which stipulates: "Lack of acknowledgement of the PCN within 30 days constitutes acceptance of the change."
- This PCN includes a **Product Discontinuation Notice** (JEDEC STANDARD "JESD48") on page 3/3

Your prompt reply will help Infineon Technologies to assure a smooth and well executed transition. If Infineon does not hear from your side by the due date, we will assume your full acceptance to this proposed change and its implementation.

Your attention and response to this matter is greatly appreciated.

Disclaimer:

If we do not receive any response by the date in the PCN above we consider this as the acceptance of the PCN.

Product / Process Change Notification



N° 2013-081-A

SUBJECT OF CHANGE: Design Change of Fluorescent Lamp Ballast Controller

PRODUCTS AFFECTED:	TYPE	SP N°	OPN	Package
	ICB2FL01G	SP000363741	ICB2FL01GXUMA1	PG-DSO-19
	ICB2FL02G	SP000555574	ICB2FL02GXUMA1	PG-DSO-19
	ICB2FL03G	SP000776684	ICB2FL03GXUMA1	PG-DSO-16
	ICB2FL04G	SP000902530	ICB2FL04GXUMA1	PG-DSO-19

REASON OF CHANGE: Improvement in functionality

DESCRIPTION OF CHANGE:	<u>OLD</u>	<u>NEW</u>
	■ <u>Deviation in functionality of Smart FL Controller ICs (see Infonote 018/13)</u>	<u>Functionality as described in datasheets</u>

PRODUCT IDENTIFICATION: via SP-ordering code

TIME SCHEDULE:

- Final qualification report: available
- First samples available: available
- Start of delivery: December 2014 – depending on customer feedback

ASSESSMENT: No negative impact on quality and reliability. No change in form and fit.

DOCUMENTATION:	2_cip13081_a	Qualification report
-----------------------	--------------	----------------------

PRODUCT DISCONTINUATION

PD13081



referring to PCN N° 2013-081-A

■ Last order date of unchanged product:	2014-08-01
■ Last delivery date of unchanged product	2014-11-30

DISCONTINUED				NEW (REPLACEMENT)			
Device	SP N°	OPN	Package	Device	SP N°	OPN	Package
ICB2FL01G	SP000363741	ICB2FL01GXUMA1	PG-DSO-19	ICB2FL01G	SP001228880	ICB2FL01GXUMA2	PG-DSO-19
ICB2FL02G	SP000555574	ICB2FL02GXUMA1	PG-DSO-19	ICB2FL02G	SP001228882	ICB2FL02GXUMA2	PG-DSO-19
ICB2FL03G	SP000776684	ICB2FL03GXUMA1	PG-DSO-16	ICB2FL03G	SP001228884	ICB2FL03GXUMA2	PG-DSO-16
ICB2FL04G	SP000902530	ICB2FL04GXUMA1	PG-DSO-19	ICB2FL04G	SP001228886	ICB2FL04GXUMA2	PG-DSO-19

If you have any questions, please do not hesitate to contact your local Sales office.