

Product Obsolescence Notification

Issue Date: 1-Jun-2021

Dear Customer:

Broadcom regrets to announce the obsolescence of the products in the table below.
Each product will have a last time buy date of **25-Nov-2021** and a last time ship of **25-May-2022**.

Please call your local sales/marketing representative to determine an appropriate replacement part available.

Part Number	MOQ
3128LG	115920
7241CPKFEB01	27636
7241BRKFEB01	27636
7241MPKFEB01-B1P	27636
7241MPKFEB01	27636
7241MVKFEB021-B1P	27636
7241MVKFEB021	27636
7241NCKFEB01-B1P	27636
7241NCKFEB01	27636
7241NCKFEB03	27636
7241UPKFEB03-B1P	27636
7241UPKFEB03	27636
7241VPKFEB07-B1P	27636
7241VPKFEB07	27636
7241ZZKFEB03-B1P	27636
7241ZZKFEB03	27636
7250NCKFEBB3-C0T	31850
7250NCKFEBB3	31850
7250TPKFEBB3-C0T	31850
7250TPKFEBB3	31850
7250UPKFEBB3-C0T	31850
7250UPKFEBB3	31850
7251SNLKFSBB3-B2T	15000
7251SNLKFSBB3	15000
7252SAFKFSBB3-C0T	17000
7252SAFKFSBB3	17000

Part Number	MOQ
7252SAPKFSBB1-C0T	17000
7252SNCKFSBB5	17000
7252SNCKFSBB5-C0T	17000
7252SRPKFSBB3-C0U	17000
7252SRPKFSBB3C0T	17000
7252SRPKFSBB3	17000
7252SUPKFSBB1-C0U	17000
7252SUPKFSBB3-B2T	17000
7252SUPKFSBB3-C0T	17000
7252SUPKFSBB3	17000
7252SUPKFSBB3-C0U	17000
7252SUPKFSBB5-B2T	15000
7252SUPKFSBB5-C0T	15000
7252SUPKFSBB5	15000
72550ZBKFEBA00A0T	47375
72604RPKFEBB0B0T	31650
7260UBKFEBB1-A0T	32625
7260ZBKFEBB0B0T	31650
7268DRKFEBB35B0T	24696
7268UBKFEBB01	24696
7268UPKFEBB03	24696
7268ZBKFEBB01-B0T	24696
7268ZBKFEBB03-B0T	24696
7278ADKFSBA00B1T	18000
7301APKFEBB1-A2P	48804
7301APKFEBB1	48804
7301RPKFEBB3-A2P	48804
7355APKFEBB3-B3P	21672
7355APKFEBB3	21672
7355VPKFEBB1-B3P	21672
7355VPKFEBB1	21672
73565APKFEBB1-A0P	23940
73565APKFEBB1	23940
73565RPKFEBB1-A0P	23940
73565RPKFEBB1	23940
73565RPKFEBB3	23940
7356APKFEBB1-B3P	22260
7356APKFEBB1	22260
7356DRKFEBB35-B3P	22260
7356DRKFEBB35	22260
7356NNKFEBB1-B3U	22260

Part Number	MOQ
7356RPKFEB1-B3P	22260
7356RPKFEB1	22260
7356ZZKFEB1-B3P	22260
7358APKFEBB1	48804
7358APKFEBB3-A2P	48804
7358APKFEBB3	48804
7358NNKFEB1-A2P	48804
7358NNKFEB1	48804
7358NNKFEB3-A2P	48804
7358NNKFEB3	48804
73625UBKFEB3-A0P	39984
7362NCKFEB3-A0P	39984
7362NCKFEB3-A0U	13300
7362NCKFEB3	39984
7362NCKFEB47-A0P	3600
7362NCKFEB47	3600
7362RPKFEB3-A0P	39984
7362RPKFEB3	39984
7362UBKFEB3A0P	2300
7362VVKFEB1-A0P	39984
7362VVKFEB1	39984
7362ZZKFEB3-A0P	39984
7362ZZKFEB3-A0U	49400
7362ZZKFEB3	49400
7362ZZKFEB1A0P	39984
7366ZBKFSBB3-C0T	10075
7366ZBKFSBB3	10075
7374MVKFSBB49-C0T	21175
7428MKKFEB1-B1P	27636
7428MKKFEB1	27636
7428NCKFEB1-B1P	27636
7428NCKFEB1	27636
7428NCKFEB5-B1P	27636
7428NCKFEB5	27636
7428TPKFEB3-B1P	27636
7428TPKFEB3	27636
7429BQKFEB1-B1P	27636
7429BQKFEB1	27636
74371CMKFEB1	29000
74371CMKFEB1-C0T	29000
74371CMKFEB1-B1T	29000

Part Number	MOQ
74371CUKFEBA1-C0T	29000
74371CUKFEBA1	29000
7444ZBKFSBB3-D3T	46500
7444ZBKFSBB3	46500
BCM7444SZBKFSBB3G	46500
7448ZBKFSBB3	10248
7449SAPKFSBB3-B2T	15000
7449SAPKFSBB3	15000
7449SBUKFSBB1	15000
7449SMGKFSBB1-B2T	15000
7449SMGKFSBB1	15000
7449SZBKFSBB1	15000
7581NCKFEBA01-B1T	40000
7581NCKFEBA01	40000
7581RPKFEBB03-B1T	40000
7581RPKFEBB03	40000
7581TPKFEBA01-B1T	40000
7581TPKFEBA01	40000
7581TPKFEBA03-B1T	40000
7581TPKFEBA03	40000
7581UPKFEBA03-B1T	40000
7581UPKFEBA03	40000
75831TPKFEBA3A1T	31654
75835TCKFEBA3A0T	29155
75835TPKFEBA3A0T	29155
75839UJKFEBA3A0T	29155
75839UPKFEBA3A0T	29155
7583ZZKFEBA3A1T	31654
75841ZZKFEBA3A1T	32340
75842LPKFEBA1A1T	32340
7584LPKFEBA1A1T	32340
7584APKFEBA1A1T	32340
7584APKFEBA3A1T	32340
7584TPKFEBA1A1T	32340
7584TPKFEBA3A1T	32340
7584UPKFEBA1A1T	32340
7584UPKFEBA3A1T	32340
7584ZZKFEBA1A1T	32340
BCM3255RKPBG	10100
BCM3410KMLG	158675
BCM3410KMLG2	158675



Part Number	MOQ
BCM3412KMLG	143375
BCM3445KMLG	65850
BCM3450IMLG	185550
BCM4551IFSBBG-B1T	43350
BCM4551IFSBBG	43350
BCM4554HIFSBBG	86250
BCM7250XCKFEBA1G	31850
BCM7250XDKFEBA1G	31850
BCM7437CVKFEBA1G	21000
BCM7437MFKFEBA1G	21000
BCM7444SAPKFSBB3G	46500
72603UPKFEBB0B0T	31650
72604FPKFEBB0B0T	31650
72604ZBKFEBB3-A0T	32625
7583TPKFEBA3A1T	31654
75842UPKFEBA3A1T	32340
75847NRKFEBA1A0T	29400
BCM4515KQLEG	68544

Please provide your Broadcom Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than **25-Nov-2021**. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy order date cannot be accepted.

The last requested delivery date for these orders may not be later than **25-May-2022** (Last Time Ship date). Due to inherent variations in yields, Broadcom reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom's minimum order quantity (MOQ) requirements per the above table. All prior commitments regarding Broadcom's minimum order requirements do not apply to last time buy orders. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.