

Product Obsolescence Notification

Issue Date: April 23, 2019

Dear [CUSTOMER]:

Broadcom regrets to announce the obsolescence of the following products:

Broadcom Part Numbers	Description	LTB Date	LTS Date	Minimum Order (MOQ)	Suggested Replacement
BCM6812IFSBG	GPON SOC	1/31/2020	7/31/2020	5030	BCM68460A1KRFBG
BCM6812KFEBG	GPON SOC	1/31/2020	7/31/2020	5030	BCM68460A1KRFBG
BCM6812RKFEBG	GPON ROUTER	1/31/2020	7/31/2020	23000	BCM68460A1KRFBG
BCM68181KFSBG	GPON SOC	1/31/2020	7/31/2020	5030	BCM68460A1KRFBG
BCM6818GKFSBG	GPON SOC	1/31/2020	7/31/2020	5030	BCM68460A1KRFBG
BCM6818KFSB	GPON SOC	1/31/2020	7/31/2020	5030	BCM68460A1KRFBG
BCM6818KFSBG	GPON SOC	1/31/2020	7/31/2020	5030	BCM68460A1KRFBG
BCM6818SRKFEBG	GPON SOC	1/31/2020	7/31/2020	23000	BCM68460A1KRFBG

*If the customer order is below the MOQ, please consult with your Broadcom Sales Office for confirmation.

Please provide your Broadcom Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy order (LTB) date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the LTS date noted in the above table. Due to inherent variations in yields, Broadcom reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom's minimum order quantity requirements per the above table. All prior commitments regarding Broadcom minimum order requirements do not apply to last time buy orders. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.