

TAIYO YUDEN

Taiyo Yuden (U.S.A.) Inc.
10 N. Martingale Road, Ste.575
Schaumburg, IL 60173
Tel (630) 237-2405 Fax (847) 240-1715
<http://www.t-yuden.com>

DISCONTINUATION NOTICE

DATE: March 6, 2012

RE: Common Mode Choke Coil (SMD) For High-speed Differential Signal
CM01 series

LAST ORDER
ACCEPTANCE: July 31, 2012. Taiyo Yuden will not accept order after this date.

REF NO.: UTY-DN12-15D

Taiyo Yuden (U.S.A.) Inc. hereby gives notice that the following Common Mode Choke Coil (SMD) For High-speed Differential Signal CM01 series will be discontinued to all distributors in North and South America. The orders will be accepted for these parts through July 31, 2012 for deliveries through September 30, 2012. Orders for these components received after the issue date of this notice are Non-Cancelable and Non-Returnable.

Discontinued Item
CM01 H900 T
CM01 S600 T
CM01 S900 T
CM01 U161 T
CM01 U900 T

NOTE: The information in this notice is applicable only to Taiyo Yuden customers in North and South America. Discontinuation schedules and availability may vary in other regions. To best serve you, all inquires and requests should be directed through the normal sales channels or you can contact the nearest Taiyo Yuden Sales Office.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department