

International Rectifier

101 North Sepulveda Boulevard, El Segundo, California, 90245, USA Telephone: +1 310 726 8000 www.irf.com

End Of Life Notification

Date: February 26, 2013
EOL Reference: EOL224
Product Reference: MLPQ Parts in Tube

To Our Valued Customer:

As always we appreciate your use of International Rectifier semiconductor products. Our commitment to customer satisfaction and continuous improvement is demonstrated by our change plans to enhance capacity, quality and reliability. This notice is to inform you of the following products which will be discontinued. We would like to express our sincere appreciation for your cooperation regarding the following changes, and IR will work closely with you to support your requirements during this transition.

Reason for Product Discontinuance:

Product portfolio rationalization and lack of demand.

IR is no longer able to manufacture these MLPQ materials in the "Tube" package type, effective immediately. Please note that the replacement product is the exact material in a Tape and Reel packing type version. If you have any open backlog on the EOL devices, please convert your order over to the Alternative Product listed below in Tape & Reel.

Energy Saving Products

Product(s) Affected: Alternate or Replacement Product(s):

| | |
|---------------|-----------------|
| IRS2093MPBF | IRS2093MTRPBF |
| IRS2001MPBF | IRS2001MTRPBF |
| IRS2053MPBF | IRS2053MTRPBF |
| IRS2113MPBF | IRS2113MTRPBF |
| IRS21814MPBF | IRS21814MTRPBF |
| IRS21844MPBF | IRS21844MTRPBF |
| IRS2334MPBF | IRS2334MTRPBF |
| IRS23365DMPBF | IRS23365DMTRPBF |



Enterprise Power Products

Product(s) Affected: Alternate or Replacement Product(s):

| | |
|-------------|---------------|
| IR3080MPBF | IR3080MTRPBF |
| IR3082AMPBF | IR3082AMTRPBF |
| IR3082MPBF | IR3082MTRPBF |
| IR3084MPBF | IR3084MTRPBF |
| IR3084UMPBF | IR3084UMTRPBF |
| IR3086AMPBF | IR3086AMTRPBF |
| IR3092MPBF | N/A |
| IR3094MPBF | IR3094MTRPBF |
| IR3500AMPBF | IR3500AMTRPBF |
| IR3500MPBF | IR3500MTRPBF |
| IR3502MPBF | IR3502MTRPBF |
| IR3504MPBF | IR3504MTRPBF |
| IR3507MPBF | IR3507MTRPBF |
| IR3513MPBF | IR3513MTRPBF |
| IR3519MPBF | IR3519MTRPBF |
| 111-3022 | IR3621MTRPBF |

Effective Dates:

| | |
|---------------------------|-------------------|
| Customer Notice: | February 26, 2013 |
| Last Time Buy*: | February 26, 2013 |
| Last Scheduled Shipment*: | February 26, 2013 |
| Final Returns Date*: | February 26, 2013 |

**International Rectifier makes no guarantee regarding quantities available for last-time-buys. Actual quantities and pricing will be negotiated on a case-by-case basis. The "Last Time Buy" is the last date IR will accept new orders for a material. The "Last Scheduled Shipment" is the date IR will attempt to fulfill all final orders, however, IR makes no guarantee that all quantities will be shipped by this date due to unforeseen supply constraints and/or acts of nature, etc. The "Final Returns Date" is the last date IR will accept a return or cancellation for a material. However, the "Final Returns Date" only applies to those materials which IR currently accepts returns and/or cancellations per IR policy or your specific customer contract and any returns and/or cancellations are subject to the terms and conditions of those policies or contracts, where applicable. Any material identified as "NCNR = Non-Cancellable, Non-Returnable" is exempt from this return and cancellation period. No returns, including stock rotations, will be accepted after the "Final Returns Date".*

Contact Information:

| Contact | Name | Phone | Email |
|----------------------|---------------|----------------|-----------------------|
| Director, Bus. Mgmt. | Shawn O'Grady | (310) 252-7186 | _____ |
| EOL Business Manager | Miriam Heath | (951) 375-4110 | _____ |