



Product Obsolescence Notification

Issue Date: 20 June 2013

OBS0620134D1

Dear Customer,

Avago Technologies regrets to announce the obsolescence of the following products.

Part Numbers Affected

1. HEDR-55L1-BH07 (Shielded cable version)
2. HEDR-55L1-BY07 (Shielded cable version)
3. HEDR-56L1-BPL9 (Shielded cable version)
4. HEDR-56L1-BY08 (Shielded cable version)
5. HEDR-58L1-B2L7 (Shielded cable version)

The Key Milestones in this obsolescence process are: -

1. **Formal customer notification beginning June 20, 2013**
2. **Final customer order date by July 19, 2013**
3. **Final ship date to customer by Sept 20, 2013**

Reasons for Obsolescence

Only these part numbers are affected by this program as the product has low demand.

Replacement Part Options

Alternative Product: There are ribbon cable versions available as replacement.

1. HEDR-55L2-BH07 (Ribbon cable version)
2. HEDR-55L2-BY07 (Ribbon cable version)
3. HEDR-56L2-BY08 (Ribbon cable version)

Please note that Avago Technologies reserves the right to limit lifetime buy quantities based on capacity and material availability. If you have any questions about this obsolescence, please do not hesitate to contact your local Avago Technologies sales representative or authorized distributors.

Motion Control Products Division
Avago Technologies

If you have any queries, please contact: SH Young, email : swee-hing.young@avagotech.com

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements.